

HI2 update 10.19

This is a minor update of the HI2 database.

A fix for the power curve of the MCHZ pumps is implemented.

Also some Combi hydraulics, introduced with update 10.18, are temporarily removed.

As soon as all parts of these pumps are on stock, the curves will be added to HI2 again.